



# مشروع إعادة إعمار الحرم الشريف للمسجد الحرام



1352

اللجنة الفنية  
تأكيد جودة الخرسانة وتطبيق السلامة

## WORK RESUMPTION ORDER (WRO)

This order is issued against the correction of IN / SWN raised for the violation of Project Safety Manual.

Date	7/3/2017	Ref. TC/HSE/WRO		
Work Resumption Order against Ref. TC/HSE/...		S-11		
Issued to:- Zone Manager/Responsible Engineer				
Name:- EWSR. Ahmed Hange				
Location	Zone:- SUB	Area:-	Level:-	Axis:-
Confirmation of Remedy/ Corrective action (by TC Safety).				
Name:-	M. Hussain	Signature:-	Date:-	Time:-
Designation:-	ISE		7/3/2017	9:15 AM
Comment/Decision:-				
1. Satisfied and resume normal work. <i>with following comments</i>				<input checked="" type="checkbox"/>
2. Not satisfied only rectification work allowed. <i>crane ± S11</i>				<input type="checkbox"/>

### Distribution;

Original	Yellow	Pink	Green
Receiver	Contractor Project Manger	Contractor Safety In-charge	TC Records

- 1- Follow PTA Procedure.
- 2- Ensured safety and crane department supervision during lifting activities.
- 3- Barricade the area radius area during lifting.

TC-ENG-SAF-QP-01-F06